




LID160 INSTALLATION




CENTRAL HINGE INSTALLATION ON GFE160

ONLY FOR LID USING


REMOVE THE MIDDLE PLATE UNDER THE GRIDDLE




INSERT THE 2 HINGE BY THE BACK





FIX THE HINGE WITH 4 SCREWS + NUTS



PLACE THE MIDDLE PLATE UNDER THE GRIDDLE





SCREW

WASHER
BETWEEN
LID AND
HINGE

SPECIAL NUT
OUTSIDE THE LID